

## PURCHASING SECTION 13450 – 104 Avenue, Surrey BC V3T 1V8 Tel: 604-590-7274

E-mail: purchasing@surrey.ca

**ADDENDUM #3** 

REQUEST FOR QUOTATIONS (RFQ) NO.: 1220-040-2017-114

TITLE: FLEETWOOD RECREATION CENTRE

**ROOF REPLACEMENT** 

ADDENDUM ISSUE DATE: November 6, 2017

**REVISED CLOSING DATE:** prefer to receive Quotations on or

before: November 15, 2017

## **INFORMATION FOR CONTRACTORS**

This Addendum is issued to provide additional information to the RFQ for the above named project, to the extent referenced and shall become a part thereof. No consideration will be allowed for extras due to the Contractor not being familiar with this Addendum. This Addendum No. 3 contains three (3) pages in total.

## **QUESTIONS AND ANSWERS**

- Q1: Can you please explain in more detail what is meant in detail VPMM184 "remove and reinstate Beauty cap apply sealant to exposed joint".
- A1: The purpose of removing the beauty cap is to ensure continuity of the air barrier by sealing to the existing metal flashing or membrane with sealant at top of the glazing system.
- Q2: Is the drip flashing on the same detail expected to be a Pittsburgh seam or segmented flashing?
- A2: The intent is for the metal drip edge flashing to be segmented flashing with the joints of the metal drip edge flashing to line up with the mullions.

- Q3: I would like clarification on the slope percentage of the taper ISO for roof section 2.1. Drawings conflict as the new composition states roof area 2.1 to have 1% slope however the actual roof section itself on the drawing shows 2%.
- A3: The intent of the specification is to have a 2% tapered Polyisocyanurate insulation slope package installed on Roof Area 2.1.

## **END OF ADDENDUM #3**

All Addenda will become part of the RFQ Documents.

